



U.S. Micro-Solutions, Inc. * 475-C Willow Crossing Road * Greensburg, PA 15601
 Phone: (724) 853-4047 Fax: (724) 853-4049 AIHA EMLAP # 103009

Customer Name: MRSA Infections, Inc.
 Customer Address:

Sample Date: October 9, 2008
 Date Received: October 10, 2008
 Date of Report: October 20, 2008

Customer Phone: (412) 555-5696
 PO Number:
 Project Number:

Fax: (412) 658-9658
 Attention:

Customer sample numbers below are uniquely identified by prefixing Laboratory # 1025-08

Bioaerosol(s) for Isolation of *Methicillin-resistant Staphylococcus aureus* - Analytical Method USMS-B002

Sample Number	Media	Sample Description	Results of Microbial Analysis
MRSA-1	SBA	Maintenance Room	<i>No Methicillin-resistant Staphylococcus aureus isolated</i>
MRSA-2	SBA	Conference Room	<i>No Methicillin-resistant Staphylococcus aureus isolated</i>
MRSA-3	SBA	Chamber's Office	<i>No Methicillin-resistant Staphylococcus aureus isolated</i>
MRSA-4	SBA	Pat's Office	<i>No Methicillin-resistant Staphylococcus aureus isolated</i>
MRSA-5	SBA	Hallway	<i>No Methicillin-resistant Staphylococcus aureus isolated</i>

Sample Report

All internal test methods are proprietary and remain the property of U.S. Micro-Solutions, Inc. (USMS). Customers are reminded that when providing duplicates of this report, the document should be provided in total. USMS shall have no liability to the Customer or the Customer's customer for opinions stated, recommendations made, actions taken, or conduct implemented by either the Customer or the Customer's customer based on the test results reported. The Customer will hold harmless and indemnify USMS for damages or lost profits of revenues because of results reported. In no event will USMS's liability of test results reported exceed the amount paid to USMS by the Customer. USMS has provided interpretation of results in good faith using the best information available at the time of the survey.

Technical Manager: Herbert Layman, BS, SM, CIEC



U.S. Micro-Solutions, Inc. * 475-C Willow Crossing Road * Greensburg, PA 15601
 Phone: (724) 853-4047 Fax: (724) 853-4049 AIHA EMLAP # 103009

Customer Name: MRSA Infections, Inc. Sample Date: October 9, 2008
 Customer Address: Date Received: October 10, 2008
 Date of Report: October 20, 2008
 Customer Phone: (412) 555-5696 Fax: (412) 658-9658
 PO Number: Attention:
 Project Number:

Customer sample numbers below are uniquely identified by prefixing Laboratory # 1025-08

Swab(s) for Isolation of *Methicillin-resistant Staphylococcus aureus* - Analytical Method USMS-B002

Sample Number	Media	Sample Description	Results of Microbial Analysis
Swab-1	MSA	Kurilko's Phone	
Analytical Sensitivity:	1 CFU/swab		No Methicillin-resistant Staphylococcus aureus isolated
Swab-2	MSA	Kurilko's Keyboard	
Analytical Sensitivity:	1 CFU/swab		No Methicillin-resistant Staphylococcus aureus isolated
Swab-4	MSA	Conf Room Printer Key	
Analytical Sensitivity:	1 CFU/swab		No Methicillin-resistant Staphylococcus aureus isolated
Swab-5	MSA	Conf Room Phone	
Analytical Sensitivity:	1 CFU/swab		No Methicillin-resistant Staphylococcus aureus isolated
Swab-7	MSA	Tindell's Phone	
Analytical Sensitivity:	1 CFU/swab		No Methicillin-resistant Staphylococcus aureus isolated
Swab-8	MSA	Chamber's Phone	
Analytical Sensitivity:	1 CFU/swab		No Methicillin-resistant Staphylococcus aureus isolated

All internal test methods are proprietary and remain the property of U.S. Micro-Solutions, Inc (USMS). Customers are reminded that when providing duplicates of this report, the document should be provided in total. USMS shall have no liability to the Customer or the Customer's customer for opinions stated, recommendations made, actions taken, or conduct implemented by either the Customer or the Customer's customer based on the test results reported. The Customer will hold harmless and indemnify USMS for damages or lost profits of revenues because of results reported. In no event will USMS's liability of test results reported exceed the amount paid to USMS by the Customer. USMS has provided interpretation of results in good faith using the best information available at the time of the survey.

Technical Manager: Herbert Layman, BS, SM, CIEC

End of Report